

December 13, 2010

Paul Leonard
President
Hibernia Management & Development Co.
Ltd.
Suite 1000, Cabot Place
100 New Gower Street
St. John's, NL
A1C 6K3

Alan R. Brown
Vice President - East Coast
Suncor Energy Inc.
Suite 201, Scotia Centre
235 Water Street
St. John's, NL
A1C 1B6

Paul J. McCloskey
Vice President, East Coast Operations
Husky Energy
Suite 901, Scotia Centre
235 Water Street
St. John's, NL
A1C 1B6

Gentlemen:

Re: OHSI Recommendation #11 – Helicopter Fleet Size


In the OHSI Report, Commissioner Wells stated:

It is recommended that helicopter fleet size should continue to be decided by the oil operators. The Regulator should monitor the fleet size to ensure that it is sufficiently large at all times to maintain helicopter safety.

We request that you advise the OHSI Aviation Team of the criteria for current fleet size and configuration. The Team will review your current model and if necessary make recommendations for improvement as well as monitor as requirements change.

We anticipate your cooperation in this regard and ask that you promptly acknowledge receipt of this letter and confirm your undertaking to accommodate our request.

Sincerely,


Max Ruelokke, P. Eng.
Chairman & CEO

Fifth Floor, TD Place, 140 Water Street, St. John's, NL, Canada A1C 6H6
Telephone (709) 778-1400 Fax (709) 778-1473