

December 13, 2010

Paul Leonard President Hibernia Management & Development Co. Ltd. Suite 1000, Cabot Place 100 New Gower Street St. John's, NL A1C 6K3 Alan R. Brown Vice President - East Coast Suncor Energy Inc. Suite 201, Scotia Centre 235 Water Street St. John's, NL A1C 1B6

Paul J. McCloskey Vice President, East Coast Operations Husky Energy Suite 901, Scotia Centre 235 Water Street St. John's, NL A1C 1B6

Gentlemen:

Re: OHSI Recommendation #18 - Risk Management Verification

In the OHSI Report, Commissioner Wells stated:

It is recommended that the Regulator continue to verify the riskmanagement practices of the oil operators and the helicopter operator(s) on an ongoing basis.

We request that the Operators ensure resources and personnel are available from their operations, helicopter operators and offshore workforce to be part of the OHSI Safety Team which will recommend how risk management assessment can be added to regular audit processes, including audit of helicopter operators which are within the Board's mandate. These assessments should be carried out in conjunction with Transport Canada's risk-based Safety Management System and aviation safety audits.

We will ask the OHSI Safety Team to develop a work plan for their response to this recommendation, and to present that work plan by January 31, 2011. We will also ask that they prepare and present a monthly status report of progress against the work plan.

Fifth Floor, TD Place, 140 Water Street, St. John's, NL, Canada A1C 6H6 Telephone (709) 778-1400 Fax (709) 778-1473 We anticipate your cooperation in this regard and ask that you promptly acknowledge receipt of this letter and confirm your undertaking to accommodate our request.

Sincerely,

Mex Ruelokke, P. Eng.

Chairman & CEO